

U.S. Government Services Facilities (Chillers) Ohio

HydroPlex Installation



OVERVIEW:

These three Ohio facilities had nearly identical problems. None had a comprehensive water treatment program in place, all towers required extensive maintenance to remove scale, algae and debris. All chillers were heavily scaled and operating at drastically reduced efficiency.

ACCOMPLISHMENTS:

Installation of The HydroPlex™ in each location eliminated existing scale, prevented further accumulation of scale, and eliminated algae and debris in the towers. The chillers have not required cleaning since HydroPlex installation in 1998 and have operated at design maximum efficiency since then.