

## West Park United Church of Christ Brookpark, Ohio

### CWI Installation



#### **OVERVIEW:**

The Church (which lacks full time or contracted maintenance personnel) replaced old, inefficient boilers at the end of their useful service life with new boilers. To minimize continuing maintenance needs the church also installed a scale control and corrosion treatment system. Post installation, we periodically tested to assure efficient operation and long service life.

#### **ACCOMPLISHMENTS:**

Our system assures the Church that its boilers are protected from scale and corrosion, thus securing its capital investment.